



Regina Catholic Schools

www.rcsd.ca

Miller Catholic High School

1027 College Ave.
Regina, Sk.

Contact Person: Tyler Ottenbreit
Telephone: 306-791-7213

Title: Facilities Supervisor
Email: t.ottenbreit@rcsd.ca

Date of Inventory: November 2010

1. Type of Asbestos-Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile Crocidolite	Throughout Building	Rain water leader CH20% CR5%		All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Throughout Building	Pipefitting compounds 40-60%	Crawlspace and above suspended ceilings. Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Boiler room	Boiler gaskets 80%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Boiler room	Parging 60%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Amosite	Boiler room, crawlspace & pipe chases	Lineal pipe insulation 60-70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Boiler room & Crawlspace	Firestop material 70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Boiler room – workbench	Counter top 50%	Behind locked door Maintenance only	
Chrysotile	Concourse	Ceiling texture 10%	Exposed	Moderate condition and recommended to manage in place until renovation warrants removal

Chrysotile	Concourse	Ceiling texture overspray 10%	Above suspended ceilings. Maintenance only	
Chrysotile Amosite	Media Centre – 110, Welding, Band, 122, 122B, B054	Spray-applied fireproofing CH- 20% AM-40%	Above suspended ceilings. Maintenance only	
Chrysotile	Room 283, B260, B092, B263, B280, B282, B283	Black countertop 30%	Exposed Non-friable	Moderate condition and recommended to manage in place until renovation warrants removal
Chrysotile	A161, A162, A167, A168, A169, A170, A280, B057, B064, B065, B,070, B092, B162, B180, B183, B190, B267, B291, B293, C191, 180, 180A, 180B, Band, Corridor in “C block”, stairwell by A280, West Entrance	Flooring 1-5%	Sealed floor	Moderate condition and recommended to manage in place until renovation warrants removal
Chrysotile	Cafeteria	Flooring 30%	Sealed floor	Moderate condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout Building	Block walls		All concrete block walls are assumed to have ACM