

St. Catherine

150 Brotherton Ave. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-551-8896 Email: t.ottenbreit@rcsd.ca

Date of Inventory: October 2012, Revised May 2019

 Type of Asbestos- 	Location in Facility	Characteristics	4. Accessibility	5. Comments
Containing Material				
Chrysotile	Crawlspace	Pipefitting compound	Behind locked door	All accessible locations marked with RED
		60-70%	Maintenance only	spray paint. All other locations assumed
				to have ACM
Chrysotile	Crawlspace – loose on ducting	Pipefitting compound	Behind locked door	
	adj. stairs. Furnace room – top	20%	Maintenance only	
	of duct and South wall			
Chrysotile	Throughout building	Transite Rainwater		All accessible locations marked with RED
Crocidolite		Leader		spray paint. All locations considered to
		CH-20% CR-5%		have ACM
Chrysotile	Damaged in Ceiling space adj.	Transite Rainwater	Above ceiling tiles	
Crocidolite	rooms 5&6	Leader	Maintenance only	
		CH-20% CR-5%		
Chrysotile	Main corridor, Classrooms 1-4	Flooring	Sealed floor	All in moderate condition and
	& 8, 9, 10. Staff and Nurses	30-40%		recommended to manage in place until
	washrooms, Staffroom, book			renovation warrants removal
	storage, Copy room, gym			
	storage, community office			
Vermiculite	Throughout interior and	Walls		Some block walls are confirmed, and all
	exterior block walls	>0.1%		other walls are assumed to have ACM
		Actinolite/Tremolite		