

## St. Luke

625 Elphinstone St. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: May 2013

Type of Asbestos- Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Furnace room, crawlspace, storage room w/ crawlspace access	Pipefitting compound 40-60%	Behind locked door Maintenance Only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Furnace room, crawlspace, storage room w/ crawlspace access	Lineal pipe insulation 70%	Behind locked door Maintenance Only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Throughout building	Transite Rainwater Leader CH-30%		All locations considered to have ACM
Chrysotile	Photo copy rm, all storage rooms, girls washroom, gym vestibule, rm's 102, 104 & 110	Flooring 1-5%	Sealed floor	All in good condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM