

Catholic Education Centre

2160 Cameron St. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: November 2010

Type of Asbestos- Containing Material	Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Basement	Pipefitting Compound 10% and 70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement	Lineal Pipe Insulation 60%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Crocidolite	Basement	Transite Rainwater Leader	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to
Si delidente		CH-20% CR-5%		have ACM
Chrysotile	Crawlspace	Pipefitting Compound 10% and 70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Crawlspace	Lineal Pipe Insulation 60%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Crawlspace	Transite Rainwater	Behind locked door	All accessible locations marked with RED
Crocidolite		Leader CH-20% CR-5%	Maintenance only	spray paint. All other locations assumed to have ACM
Chrysotile	Main floor – North Entrance	VCT 1-5%	Sealed Floor	

Chrysotile	Main floor	Pipefitting Compound	Above suspended ceiling	All accessible locations marked with RED
		70%	Maintenance only	spray paint. All other locations assumed to
				have ACM
Chrysotile	Main Floor	Transite Rainwater	Above suspended ceiling	All accessible locations marked with RED
Crocidolite		Leader	Maintenance only	spray paint. All other locations assumed to
		CH-20% CR-5%		have ACM
Main Floor	Crawlspace	Lineal Pipe Insulation	Behind locked door	All accessible locations marked with RED
		60%	Maintenance only	spray paint. All other locations assumed to
				have ACM
Chrysotile	Second Floor	Pipefitting Compound	Above suspended ceiling	All accessible locations marked with RED
		70%	Maintenance only	spray paint. All other locations assumed to
				have ACM
Chrysotile	Second Floor	Transite Rainwater	Above suspended ceiling	All accessible locations marked with RED
Crocidolite		Leader	Maintenance only	spray paint. All other locations assumed to
		CH-20% CR-5%		have ACM
Chrysotile	Second Floor	Lineal Pipe Insulation	Behind locked door	All accessible locations marked with RED
		60%	Maintenance only	spray paint. All other locations assumed to
				have ACM
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have
				ACM