

## St. Mary

140 N McIntosh St. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: October 2012

1. Type of Asbestos-	2. Location in	3. Characteristics	4. Accessibility	5. Comments
Containing Material	Facility			
Chrysotile	West Furnace room	Duct expansion gasket	Behind locked door	All accessible locations marked with RED spray
		60%	Maintenance only	paint.
Chrysotile	Furnace rooms	Pipefitting Compound	Behind locked door	All accessible locations marked with RED spray
		60%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Crawlspace	Pipefitting Compound	Behind locked door	All accessible locations marked with RED spray
		30%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Corridors	Pipefitting Compound	Above ceiling tiles	All accessible locations marked with RED spray
		80%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Throughout building	Transite Rainwater		All locations assumed to have ACM
		Leader and Pipefitting		
		Compound 30%		
Chrysotile	Gym, Planning room,	Flooring	Sealed floor	Moderate condition and recommended to
		1-5%		manage in place until renovation warrants
				removal
Chrysotile	Copy Room	Flooring	Sealed floor	Moderate condition and recommended to
		30%		manage in place until renovation warrants
				removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM