

St. Peter

150 Argyle St. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: May 2013

1. Type of Asbestos-	2. Location in	3. Characteristics	4. Accessibility	5. Comments
Containing Material	Facility			
Chrysotile	Mechanical Rooms	Pipefitting Compound	Behind locked door	All accessible locations marked with RED spray
		50%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Mechanical Rooms	Duct expansion gasket	Behind locked door	All accessible locations marked with RED spray
		40%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Mechanical Rooms	Mud compound in	Behind locked door	All accessible locations marked with RED spray
		water tank insulation	Maintenance only	paint
		70%		
Chrysotile	Boiler room	Fire stop material	Behind locked door	All accessible locations marked with RED spray
		60%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Boiler room	Lineal insulation and	Behind locked door	All accessible locations marked with RED spray
		pipefitting compound	Maintenance only	paint. All other locations assumed to have ACM
		30%		
Chrysotile	Throughout building	Pipefitting Compound	Above ceiling space	All accessible locations marked with RED spray
		50%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Lobby	Heat shield from light	Ceiling height	
		80%	Maintenance only	
Chrysotile	Throughout building	Transite Rainwater		All locations assumed to have ACM
		Leader 30%		

Chrysotile	Entrance, Main hallways,	Flooring	Sealed floor	Good - moderate condition and recommended
	storage rooms,	1-5%		to manage in place until renovation warrants
	classrooms P02,PO9,			removal
	102,105,108,109,110,111,			
	204,301,303,305,306,307,			
	308,gym			
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have
				ACM