



# Regina Catholic Schools

www.rcsd.ca

## Holy Rosary

3118 – 14 Avenue  
Regina, Sk.

Contact Person: Tyler Ottenbreit  
Telephone: 306-791-7213

Title: Facilities Supervisor  
Email: t.ottenbreit@rcsd.ca

Date of Inventory: November 2010

1. Type of Asbestos-Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Basement	Pipefitting Compound 20% and 70%	Behind locked doors and above suspended ceilings Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement	Lineal Pipe Insulation 60%	Behind locked doors and above suspended ceilings Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Crocidolite	Basement	Transite Rainwater Leader CH-20% CR-5%	Behind locked doors and above suspended ceilings Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement	9x9 floor tiles Throughout 1-5%	Sealed floor	
Chrysotile	Basement Boiler Room- small exit	Fire Stop Material 60%	Behind locked doors Maintenance only	All accessible locations marked with RED spray paint.
Chrysotile	Basement Boiler Room	Boiler insulation 80%	Behind locked doors Maintenance only	All accessible locations marked with RED spray paint.

Chrysotile	Crawlspace	Pipefitting Compound 10% and 70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Crawlspace	Lineal Pipe Insulation 60%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Crocidolite	Crawlspace	Transite Rainwater Leader CH-20% CR-5%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Main floor –West Corridor	Sheet Vinyl 40%	Sealed floor	
Chrysotile	Main floor	Pipefitting Compound 70%	Above suspended ceiling Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Crocidolite	Main Floor	Transite Rainwater Leader CH-20% CR-5%	Above suspended ceiling Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Main Floor	Lineal Pipe Insulation 60%	Above suspended ceiling Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Second Floor	Pipefitting Compound 70%	Above suspended ceiling Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Crocidolite	Second Floor	Transite Rainwater Leader CH-20% CR-5%	Above suspended ceiling Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Second Floor	Lineal Pipe Insulation 60%	Above suspended ceiling Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM