



Regina Catholic Schools

www.rcsd.ca

St. Andrew

621 Douglas Ave.
Regina, Sk.

Contact Person: Tyler Ottenbreit
Telephone: 306-791-7213

Title: Facilities Supervisor
Email: t.ottenbreit@rcsd.ca

Date of Inventory: October 2012

1. Type of Asbestos-Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Gym storage room	Pipefitting Compound 20%	Behind locked door	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement	Pipefitting Compound 40%	Above ceiling tile Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement- Boiler room	Lineal pipe insulation 70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement – Boiler Room	Pipefitting Compound 30-40%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Rooms 101, 102, 108 109, Caretaker room, storage under gym & LRP	Flooring 1-5%	Sealed floors	All in moderate condition and recommended to manage in place until renovation warrants removal
Vermiculite Actinolite/Tremolite	Throughout	Block walls	+0.1%	All concrete block walls are assumed to have ACM