



Regina Catholic Schools

www.rcsd.ca

St. Matthew

4710 Castle Rd.
Regina, Sk.

Contact Person: Tyler Ottenbreit
Telephone: 306-791-7213

Title: Facilities Supervisor
Email: t.ottenbreit@rcsd.ca

Date of Inventory: October 2012

1. Type of Asbestos-Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Crawlspace and Furnace rooms	Fire stop material 60%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Crawlspace and Furnace rooms	Pipefitting Compound 20-30%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Crawlspace and Furnace rooms	Lineal pipe insulation 60%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Corridors	Roof drain Pipefitting Compound 40%	Above ceiling tiles Maintenance only	All other locations assumed to have ACM
Chrysotile	Throughout building	Transite Rainwater Leader and Pipefitting Compound 30%		All locations assumed to have ACM
Chrysotile	All storage rooms, rm 12 &13, All caretaker rooms, Multi-purpose	Flooring 1-5%	Sealed floor	Moderate condition and recommended to manage in place until renovation warrants removal
Chrysotile	Nurses Room, Kindergarten	Flooring 30%	Sealed floor	Moderate condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM

