

St. Pius

3301 Garnet St. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: October 2012

Type of Asbestos- Containing Material	Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Throughout Building	Stipple ceiling texture 20%	Most Above ceiling tiles. Some exposed	
Chrysotile	Boys and Girls washrooms	Pipefitting Compound 50%	Above ceiling space Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Throughout building	Transite Rainwater Leader 30%		All locations assumed to have ACM
Chrysotile	South stairwell, gym, gym washrooms and change rooms, gym storage, caretaker room	Flooring 1-5%	Sealed floor	Good - moderate condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM