

## St. Timothy

280 Sangster Blvd. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: May 2013

1. Type of Asbestos-	2. Location in	3. Characteristics	4. Accessibility	5. Comments
Containing Material	Facility			
Chrysotile	Boiler room	Mud compound	Behind locked door	All accessible locations marked with RED spray
		60%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Boiler Room / Crawlspace	Duct expansion gasket	Behind locked door	May be more under yellow insulation on all
		30%	Maintenance only	mechanical ducting
Chrysotile	Throughout building	Transite Rainwater		All accessible locations marked with RED spray
		Leader		paint. All locations assumed to have ACM
		30%		
Chrysotile	Gym, all storage rooms,	Flooring	Sealed floor	Good - moderate condition and recommended
	staff washrooms,	Tile 1-5%		to manage in place until renovation warrants
	kindergarten washroom	Sheet 40%		removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have
				ACM