



Regina Catholic Schools

www.rcsd.ca

Sacred Heart

1314 Elphinstone St.
Regina, Sk.

Contact Person: Tyler Ottenbreit
Telephone: 306-791-7213

Title: Facilities Supervisor
Email: t.ottenbreit@rcsd.ca

Date of Inventory: November 2010

1. Type of Asbestos-Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Crawlspace	Pipefitting Compound 25-30%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile Crocidolite	Crawlspace	Transite Rainwater Leader CH-20% CR-5%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement	Lineal pipe insulation 70%	Above ceiling tile Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement- North Storage Room	Lineal pipe insulation 70%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement – Boiler Room	Mud Compound 80%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM
Chrysotile	Basement – Boiler Room	Pipefitting Compound 30-40%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to have ACM

Chrysotile	Main floor- Caretaker room	Flooring 30%	Sealed floor, Behind locked door. Maintenance only	All in moderate condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM