

St. Joan of Arc

10 Dempsey Ave. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: May 2013

Type of Asbestos- Containing Material	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Basement – Boiler Room	Duct expansion gasket 45%	Behind locked doors Maintenance only	All accessible locations marked with RED spray paint. There may also be more under the yellow insulation
Chrysotile	Main Corridor	Stipple Ceiling 5%		All in good condition and recommended to manage in place until renovation warrants removal
Chrysotile	Throughout building	Transite Rainwater Leader CH-30%		All locations considered to have ACM
Chrysotile	Gym corridor- Boxes in crawlspace	Flooring 1-5%	Sealed floor	Some need to be replaced with stock from crawlspace
Chrysotile	Caretaker office, gym storage, Boys and girls change rooms, storage rooms, copy room	Flooring 1-5%	Sealed floor	All in good condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM